THE LOCATION OF CESSPOOLS, WELLS AND OTHER UNDERGROUND INSTALLATIONS, IF ANY, ARE SHOWN IN ACCORDANCE WITH SOURCES BELIEVED TO BE ACCURATE. HOWEVER, THIS OFFICE DOES NOT ASSUME RESPONSIBILITY FOR THEIR ACCURACY.

CLEARING
Allowed - 15,300 sq ft
Existing - 13,560 sq ft


D-3937-536-154
812-76
1014-64

LOTS 6 thru 15; BLOCK 10
KINGSTOWN PARK
SECTION 2

Filed July 8, 1912 as map no 365
Situate
Springs, Town of East Hampton,
Suffolk County, New York
Scale 1"=40'

AREA = 20,000 sq ft

certified to: Doreen Kite



Note:
1) Unauthorized alteration or addition to a survey map bearing a licensed surveyor's seal is a violation of section 7209 of the New York State Education Law.
2) Only copies from the original of this survey map bearing an original land surveyor's embossed seal shall be considered to be a valid copy.
3) Certifications indicated hereon shall run only to the person for whom the survey is prepared, and on his/her behalf to the title company, governmental agency and lending institution listed hereon. Certifications are not transferable to additional institutions or subsequent owners. Certifications indicated hereon signify that this survey was prepared in accordance with [illegible] of practice for land surveys [illegible] State Association of Professional [illegible]
4) The existence of subsurface improvements or encroachments, or wetlands, or easements, covenants, or restrictions of record, if any, not shown are not certified.

Revised: June 1, 2005 - Red Final
Revised: August 15, 1988 - stk Red
Revised: August 16, 1988 - Deck
Revised: August 1, 1988 - Gar
Revised: June 28, 1988 Patio Shower
Revised: July 8, 1975 Bldg Gar
Revised: May 21, 1975
Revised: Feb. 6, 1975
Surveyed: Jan 16, 1975

GEORGE WALBRIDGE SURVEYORS, P.C.
Land Surveyors & Land Planners
East Hampton, New York